




亏.2





| | TEMPERATURE (°C) | TIME (SECOND) | HEATING MODE |
|----------------------------|--|--------------------------------|--|
| 1 2 3 4 5 6 | 150 250 1000 1000 2300 2500 | 20 10 10 10 2 2 | RUMP RUMP RUMP STEP STEP STEP |

(PRIOR ART)



Fy-6 (PRIOR ART)